COMPLETION REPORT

1	Name of the work	Maintenance of Borewell at Sidedahalli Village limit in Bagalagunte ward No. 14
2	Sanctioned Estimate No. & Date	T.S.No 14/15-16 dt 6-1-2016
3	Head of Account which is chargeable	P-Cr 1771
4	Instrument Order NO. & Date	WONo 70/15-16 dt 24.3.2016
5	Name Of Contractor	Sri. Doddanarasegowda V.K, # 333, Venugopalaswamy temple road, Bagalagunte, Bangalore-560073
6 a	Time Stipulated for Completion of work	
b	Delay in Exculpation of Work	
7	Measurement recorded in	MB No 1721 PNo 172055 to 172058
8	Check Measurement of the Asst	
9	Name of the office/official in charge of the work	
10	a) Asst. Eng/junior Eng	[illegible]
	b) Asst. Exe Engineer	[illegible]

Sanctioned Estimate Amout	Amout Claims As per Actually Vide As per bills	Excess	Savings
5.00	4641382	—	358618

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER.

ASSIATANT EXECUTIVE ENGINEER